

## FD-B4S

Highly flexible 7-axis high-speed robot with integrated cable routing for welding, manufacturing and handling The 7-axis arc welding robot B4S from the FD series is compact and, thanks to the integrated cable routing, offers optimal protection during the work process. The extended degree of freedom enables a constant torch orientation when immersing in tight work spaces.

Specification		
Туре	FD-B4S	
Number of axes	7	
Working range	R 1435mm	
Max. payload capacity	4 Kg	
Additional payload capacity Axis 3	10 Kg	
Installation type	F	
Weight	189 Kg	
Ambient temperature and humidity	$0 \sim 45$ °C, $20 \sim 80$ % RH (No condensation)	



## **Product information**

Order No. 116000008

Model No. 0

## **Performance**

Position repeatability (ISO 9283) +/- 0,08 mm (Note 1)

	Working Range	Max Speed	Wrist load
Axis 1	+/- 170°	3,66 rad/s {210°}	
Axis 2	- 145° ~ + 70°	3,66 rad/s {210°}	
Axis 3	- 170° ~ + 142,6°	3,66 rad/s {210°}	
Axis 4	+/- 155°	7,33 rad/s {420°}	0,38 kg/m²
Axis 5	- 45° ~ + 225° (Note 6)	7,33 rad/s {420°}	0,38 kg/m²
Axis 6	+/-205° (Note 6)	10,5 rad/s {600°/s}	0,03 kg/m²
Axis 7	+/- 90°	3,14 rad/s {180°/s}	

Note 1: The value of the positional repeatability is at the tool center point (TCP) compliant to ISO 9283.

F= Floor W=Wall C=Ceiling

Note 2: The value in the parentheses indicates the wall-hung condition. J2 axis may occur the limitation of the working range.

Note 3: There are occasions where restrictions can be made to the operation range of the J2 axis when the wall-hung condition.

Note 4: The operation range of the J3 axis is restricted to -170 degrees to +180 degrees when floor based welding is applied (In overhead mounting it's a combination of J2 + J3 degrees when floor based welding is applied (In overhead mounting it's a combination of J2 + J3 degrees when floor based welding is applied (In overhead mounting it's a combination of J2 + J3 degrees when floor based welding is applied (In overhead mounting it's a combination of J2 + J3 degrees when floor based welding is applied (In overhead mounting it's a combination of J2 + J3 degrees when floor based welding is applied (In overhead mounting it's a combination of J2 + J3 degrees when floor based welding is applied (In overhead mounting it's a combination of J2 + J3 degrees when floor based welding is applied (In overhead mounting it's a combination of J2 + J3 degrees when floor based welding is applied (In overhead mounting it's a combination of J2 + J3 degrees when floor based welding it is a combination of J2 + J3 degrees when floor based welding it is a combination of J2 + J3 degrees when floor based well degrees whe

Note 5: This is the specification for the case that the coaxial power cable are let into the centrum of J4 and J6 axis. The value given in parentheses presents for other specifications.

Note 6: There are occasions where restrictions can be made to the operation range of the J6 axis, depending on the J5 axis's posture.

Note 7: Max. Load to the upper shoulder, when loading the max. payload capacity at the end effector.